

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-24831
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. Indicate Type of Lease STATE ☐ FEE ☒
2. Name of Operator SHELL WESTERN E&P INC.		6. State Oil & Gas Lease No.
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)		7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT
4. Well Location Unit Letter F : 1980 Feet From The NORTH Line and 1980 Feet From The WEST Line Section 3 Township 21S Range 37E NMPM LEA County		8. Well No. 108
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3479' GR		9. Pool name or Wildcat NORTH LUNICE BLINEBRY-TUBB-DRINKARD OIL & GAS

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: Attmpd cmt sqz; TA'd ☒	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-03 to 11-09-89:

POH w/prod equip. Tagged PBTD @ 6770'. Set CIBP @ 6430' & PKR @ 6410'. Pres tstd CIBP to 1000#, held OK. Pulled PKR to 6230' & estab inj rt. POH w/pkr. Set cmt ret @ 6224'. Attmpd to sqz Tubb perfs 6253'-6394' w/50 SX CIs "C" cmt + .39% CF-1 followed by 50 SX CIs "C" cmt + 2% CaCl₂. Didn't obtain sqz. Overdispl cmt. Couldn't sting out of ret. Chem cut tbg @ 4430'. Mld over fish to 4509'. RIH w/overshot. Couldn't pull into fish. RIH w/1-11/16" sinker bar. Couldn't get below 4462'. POH w/WL, tbg & tools. Rec 15' piece of cut-off tbg. RIH w/overshot & latched onto fish. RIH w/sinker bar. Couldn't get below 4462'. RD WL. Tagged top of fill @ 4463'. Drld/mld out cmt, metal & fill to 4489', fell out. Tagged cmt ret @ 6224'. Ran CBL from 6215' to 4400'. Log indicated cmt from 4508' to 5400'. POH w/overshot. Mld over

(CONT'D ON REVERSE SIDE)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *J. H. Smitherman* TITLE REGULATORY SUPV. DATE 1-04-90
TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

TA expires 1-1-91

JAN 17 1990

fish 4459' - 4480'. Retagged fish @ 4458'. Latched onto fish. Fish came free.
Rec 15' tbg fish. Tagged top of fish @ 4484', md to 4628' (tod torqueing up).
Obtained approval from NMOC's Mr. Jerry Sexton to TA well. Circ'd inhib fluid.
Performed 30-min pres tst on csg, held OK. Installed WH. Well is TA'd.

RECEIVED

JAN 16 1990