ENERGY AND MINERALS DEPARTMENT	
DISTRIBUTION P. O. BOX 2088 SANTA FE SANTA FE, NEW MEXIC	Form C-103 Revised 10-
FILE U.S.O.S. LAND OFFICE OPERATOR	State X Fee State Oil & Gas Lease No. B-1167
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN OR PLUG BACK TO A D USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSA	ALS.)
OIL X GAS OTHER-	7. Unit Agreement Name
2. Name of Operator HANSON OPERATING COMPANY, INC.	8. Form of Lease Name SHELL STATE
P. O. BOX #1515, ROSWELL, NEW MEXICO 88202-1515	9. Well No. 5 #1
4. Location of Well UNIT LETTER 0 1650 PEET FROM THE East LINE A	10. Field and Pool, or Wildcat Blinebry & Drinkard
THE South LINE, SECTION 36 TOWNSHIP 21-S RAN	
15. Elevation (Show whether DF, RT, C 3493.2' GR	GR, etc.) 12. County Lea
Check Appropriate Box To Indicate Nature of NOTICE OF INTENTION TO:	of Notice, Report or Other Data SUBSEQUENT REPORT OF:
PULL OR ALTER CABING CASING T	ALTERING CASING NCE DRILLING OPNS. PLUG AND ABANDONMENT TEST AND CEMENT JQB
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and g work) SEE RULE 1103. Temporarily abandon Drinkard formation by setting Acidize Blinebry perforations @ 5514 - 5841' w/5 by 3000 gals 15% NEFE w/scale inhibitor.	ng permanent BP @ 6025'+.
·	