ENERGY AND MINERALS DEPARTMENT	
'L CONSERVATION DIVISIC	
DISTRIBUTION P. O. BOX 2088	Form C-103 Revised 19-1-7
SANTA FE, NEW MEXICO 87501	
FILE	5a. Indicate Type of Lease
U.\$.o.\$.	State XX Fee
LAND OFFICE	5. State Oil 6 Gas Lease No.
OPERATOR	B-1167
	mmmmm
SUNDRY NOTICES AND REPORTS ON WELLS THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	
1.	7. Unit Agreement Name
01L Y 6A5	
2. Name of Operator	8. Farm or Lease Name
HANSON OPERATING COMPANY, INC.	SHELL STATE
	9. Well No.
P. O. BOX #1515, ROSWELL, NEW MEXICO 88202-1515	#2
	10. Field and Pool, or Wildcat
4. Location of Well	Blinebry & Drinkard
UNIT LETTER J 1980 FEET FROM THE SOUTH LINE AND 1650	FROM CONTROLLED
THE East LINE, SECTION 36 TOWNSHIP 21-S RANGE 36-E	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea
3496.9' GR	Tea /////////
16. Check Appropriate Box To Indicate Nature of Notice, Report of	r Other Data
• • • • • • • • • • • • • • • • • • •	JENT REPORT OF:
NOTICE OF INVENTION 101	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
Ty Duidland formation	PLUG AND ABANDONMENT
	1
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JUB CASING TEST	·
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incl	uding estimated date of starting any proposed
work) see rule 1103.	
Temporarily abandon Drinkard formation by setting permanent BP	@ 6025' - .
Acidize Blinebry perforations @ 5574 - 5738' w/500 gals Gypsol,	followed
by 3000 gals 15% NEFE w/scale inhibitor.	
by 5000 gais 15% Hill wy sedie 1111	
·	

Brenda P. Witt	Producti	ion Analyst DATE 10/16/84
	,	00T 1 8 198
ED DY	TITLE	DATE