

Submit 3 Copies to Appropriate District
Office

DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II

811 South First, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

DISTRICT IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

FORM C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL APT NO. 30-025-25008
1. Type of Well: <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER Injection		5. Indicate Type of Lease <input type="checkbox"/> STATE <input checked="" type="checkbox"/> FEE
2. Name of Operator Apache Corporation		6. State Oil & Gas Lease No. 22503
3. Address of Operator 2000 Post Oak Blvd., Ste. 100, Houston, Texas 77056-4400		7. Lease Name or Unit Agreement Name Northeast Drinkard Unit
4. Well Location Unit Letter E : 2080 Feet From The North Line and 660 Feet From The West Line Section 3 Township 21S Range 37E NMFM Lea County		8. Well No. 105
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3478' GR		9. Pool name or Wildcat Eunice N., Blinbry-Tubb-Drinkard

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

- | | |
|--|---|
| <input type="checkbox"/> Perform Remedial Work | <input type="checkbox"/> Plug and Abandon |
| <input type="checkbox"/> Temporarily Abandon | <input type="checkbox"/> Change Plans |
| <input type="checkbox"/> Pull or Alter Casing | |
| <input type="checkbox"/> Other | |

- | | |
|---|---|
| <input type="checkbox"/> Remedial Work | <input type="checkbox"/> Altering Casing |
| <input type="checkbox"/> Commence Drilling Operations | <input type="checkbox"/> Plug and Abandonment |
| <input type="checkbox"/> Casing Test and Cement Job | |
| <input checked="" type="checkbox"/> Other | Clean out wellbore & Acidize |

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 11/8/99 MIRU NU BOP. Release injection packer and POH w/ injection string.
- 11/9/99 Run in hole w/ 2-7/8" workstring to 6672'. Clean out fill to 6842'. Circulate hole clean.
- 11/10/99 Acidize Drinkard perforations 6547 - 6813 w/ 4000 gals 15% HCL
Acidize Blinbry perforations 5791 - 6199 w/ 3000 gals 15% HCL
- 11/11/99 RIH w/ 5-1/2" Guiberson Uni-6 packer and 2-3/8" tubing. Set packer @ 5734'. Return well to injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Debra J. Anderson TITLE Sr. Engineering Technician DATE 2/22/00
TYPE OR PRINT NAME Debra J. Anderson TELEPHONE NO. _____
(This space for State Use)

APPROVED BY

ORIGINAL SIGNED BY
GARY W. WINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

FEB 11 2003

CONDITIONS OF APPROVAL, IF ANY:

LAST CHART PERFORMED - KAY

