

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-25008
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT
8. Well No. 105
9. Pool name or Wildcat NORTH EDNICE BLINEBRY-TUBB- DRINKARD OIL & GAS

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER ☐ INJECTOR ☐	
2. Name of Operator SHELL WESTERN E&P INC.	
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	
4. Well Location Unit Letter <u>E</u> : <u>2080</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>3</u> Township <u>21S</u> Range <u>37E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3486' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: <u>REP BRADENHEAD LK</u> ☒	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. PCH w/inj equip.
2. Set CIBP @ 4300'.
3. Pres tst csg to 500#. If csg does not hold, isolate lk & notify engr.
4. Perf 4-way shot @ 1430'.
5. Etab circ dwn csg & out 8-5/8" bradenhead.
6. Set CIRC @ 1350'.
7. Sqz bradenhead w/100 sx Cls "C" cmt + 5#/sk Gilsonite + 3#/sk salt + .7% CF-1 followed by 125 sx Cls "C" cmt + 1% CaCl₂. Circ cmt to surf. WOC.
8. DO CIRC & cmt. Pres tst sqz to 300#.
9. DO CIBP @ 4300' & push to btm (6834').
10. Install inj equip, setting Guib Uni-VI Pkr @ ±5750'. Pres tst csg to 300# for 30 min. Ret to inj.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. SMITHERMAN TITLE REGULATORY SUPV. DATE 1-18-90
TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I CHAIRMAN TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

JAN 23 1990