NO. OF COPIES RECEIVED						
DISTRIBUTION	DISTRIBUTION NEW MEXICO OIL CONSERVATION COMMISSION			Form C-101		
SANTA FE			_	Revised 1-1-65		
FILE				5A. Indicate Type of Lease		
U.S.G.S.						
LAND OFFICE			ŀ	5. State Oil & Gas Lease No.		
OPERATOR			Ļ			
APPLICATION F	FOR PERMIT TO DRILL, DEEPEN,	, OR PLUG BACK	- F			
1a. Type of Work				7. Unit Agreement Name		
		PLUG BA				
b. Type of Weil	DEEPEN	PLUG BA		8. Farm or Lease Name		
OIL GAS WELL	OTHER .	SINGLE MULTI	PLE	H. T. Mattern (NCT-C)		
2. Name of Operator				9. Well No.		
Gulf Oil Corporation	n			11		
3. Address of Operator		10. Field and Pool, or Wildcat				
P. O. Box 670, Hobb		Drinkard /				
4. Location of Well	<u>M</u> LOCATED 376	south	LINE			
UNIT LETTER_	LOCATED	FEET FROM THE				
	0	TWP. 215 RGE. 371	• ммрм			
AND 660 FEET FROM THE	E West LINE OF SEC. 8	TWP. $21S \text{ rge}$. $3/1$	innn	12. County		
				Lea		
		+++++++++++++++++++++++++++++++++++++++	<i>\}}}}}</i>	TTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTT		
(1))))))))))))))))))))))))))))))))))))						
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	*************	19. Proposed Depth 19	A. Formation	20. Rotary or C.T.		
ΛΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙ		Blinebr				
21. Elevations (Show whether DF, RT	(, etc.) 21A. Kind & Status Plug. Bond	21B. Drilling Contractor		22. Approx. Date Work will start		
3495' GL	Blanket					
23. PROPOSED CASING AND CEMENT PROGRAM						

SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CEMENT	EST. TOP
12-1/4"	8-5/8"	24.0#	1312'	550	Circ.
7-7/8"	5-1/2"	15.5#	6800'	2185	Circ.
		DV tool at	3296'		

Pull producing equipment. Run $5\frac{1}{2}$ " CIBP and set at 6500', temporarily abandoning Drinkard pay. Test CIBP to 750#. Perforate Blinebry intervals at 5536-38', 5578-80', 5642-44', 5678-80', 5721-23' and 5813-15' with 2, $\frac{1}{2}$ " JHPF. Run treating equipment. Straddle and acidize each set of Blinebry perforations with 200 gallons 15% inhibited iron stabilized HCl acid. Swab and/or flow back acid residue. Frac treat Blinebry perforations 5536-5815' in 6 stages with 42,000 gallons gelled water, 18,000# 100 mesh sand and 66,000# 20-40 sand. Pump 200 gallons 15% HCl acid between each stage, diverting with 7/8" ball sealers between stages. Swab and/or flow back all load. Pull treating equipment and run producing equipment. Swab well and clean up. Return well to production.

Will down hole commingle at a later date under Administrative Order No. DHC-254.

IN ABOVE SPACE DESCRIBE PROPOSED PROGRAM: IF PROPOSAL IS TO DEEPEN OR PLUG BACK, GIVE DATA ON PRESENT PRODUCTIVE ZONE AND PROPOSED NEW PRODUC TIVE ZONE, GIVE BLOWOUT PREVENTER PROGRAM, IF ANY.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed P. Labor for	TilleArea Engineer	Date 9-18-78
(This space for State Use)	SUPERVISION LAUINAUT I	SEP 19 19/8
CONDITIONS OF APPROVAL IF ANY:		