

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes OII
C-102 and C-101
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR APPLICATION TO DRILL OR TO REOPEN OR RELOCATE TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - "A" (FORM C-101) FOR SUCH PURPOSES.)		50. Indicate Type of Lease State ☒ Fee ☐
1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		5. State Oil & Gas Lease No. B-1732
2. Name of Operator GULF OIL CORPORATION		6. Name of Lease Name W. A. Ramsay (NCT-A)
3. Address of Operator P. O. Box 670, Hobbs, New Mexico 88240		9. Well No. 51
4. Location of Well UNIT LETTER H 1980 FEET FROM THE North LINE AND 510 FEET FROM THE East LINE, SECTION 35 TOWNSHIP 21-S RANGE 36-E N.M.P.M.		10. Field and Foot, or Wildcat Eumont - Queen
15. Elevation (Show whether DF, RT, CR, etc.) 3549' GL		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☐ CHANGE PLANS ☐ OTHER ☐	REMEDIAL WORK ☐ COMMENCE DRILLING OPER. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER ☒ Abandon Drinkard Zone; Recomplete in Eumont	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5215' PB. Pull producing equipment. Set a CIBP @ 6650' & cap w/20' cmt. Perf 6303-05', 6366-68', 6412-14', 6499-6501', & 6559-61'. Acidize w/11,500 gals acid. Swab & test. (3-24-78) Tubb zone uneconomical to produce. Set a CIBP @ 6214' & cap w/35 ft cmt. (Blinebry zone) Perf 5647-49', 5697-99', 5754-56', 5814-16' & 5836-38'. Acidize w/1250 gals 15% acid (4-5-78). Blinebry zone uneconomical to produce. Set a CIBP @ 6610' & cap w/35' cmt. Perf 5-1/2" csg @ 5310-12', 5386-88', 5437-39' & 5509-11'. Paddock zone. Acidize w/1000 gals 15% NE FE acid (4-12-78). Paddock zone uneconomical to produce. Set a CIBP @ 5250' & cap w/35' cmt. Perf 5-1/2" csg w/(2) 1/2" JHPF @ 3543-45', 3566-68', 3583-85', 3610-12', 3633-35', 3659-61' & 3676-78' Eumont zone. (4-19-78) Acidize w/1750 gals 15% NE FE acid. Swabbed & tested well. Ran tbg & set @ 3712'. Ran pump & rods. Returned well to production 4-24-78. Tested 5-2-78.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED <u>N. P. Sikes, Jr.</u> Orig. Signed By Jerry Sexton Dist. I, Supv.	TITLE <u>Area Engineer</u> TITLE _____	DATE <u>5-5-78</u> DATE <u>MAY 6 1978</u>	REMOVED BY _____ CONDITIONS OF APPROVAL, IF ANY: