

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDARY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPERATE OR REEQUIP A WELL IN A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (C-101) FOR SUCH PROPOSALS.		5a. Indicate Type of Lease State ☒ Fee ☐ 5. State Oil & Gas Lease No. B-1732
1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ 2. Name of Operator Gulf Oil Corporation 3. Address of Operator P. O. Box 670, Hobbs, NM 88240 4. Location of Well UNIT LETTER H 1980 FEET FROM THE North LINE AND 510 FEET FROM THE East LINE, SECTION 35 TOWNSHIP 21-S RANGE 36-E N.M.P.M.		7. Unit Agreement Name 8. Farm or Lease Name W. A. Ramsay (NCT-A) 9. Well No. 51 10. Field and Pool, or Wildcat Blinebry
15. Elevation (Show whether DT, RT, GR, etc.) 3549' GL		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☒	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☒
OTHER Recomplete in the Paddock		OTHER Abandon Drinkard and recomplete in the Blinebry	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled producing equipment. Set a 5 1/2" CIBB at 6650' and capped with 20' cement. Abandoning the Drinkard zone. Perforate 5 1/2" casing w/ 2-1/2" JHPF at 6303-05', 6366-68', 6412-14', 6499-6501', 6559-61'. Acidized with 1750 gal 15% NE FE Hydrochloric acid. Swabbed and tested Blinebry zone. Testing indicated Blinebry zone uneconomical to produce. Now preparing to abandon the Blinebry zone and re-complete in the Paddock zone.

Set a CIBP at 5600' and cap with 35' cement. Perforate 5 1/2" casing w/ 2-1/2" JHPF at 5310-12', 5386-88', 5437-39', and 5509-11'. Straddle acidize Paddock perms with 250 gal 15% NE iron stab HCL acid per set. Swab and test well. Return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>H. P. Sikes, Jr.</u>	TITLE <u>Area Engineer</u>	DATE <u>4-10-78</u>
RECEIVED BY <u>J. C. Cotton</u>	TITLE <u></u>	DATE <u>APR 13 1978</u>
CONDITIONS OF APPROVAL, IF ANY <u></u>		