

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-

3a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.  
L-922

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OCCUPY OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

|                                                                                                                                                                                                           |                                                |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------|
| 1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER                                                                                          | 7. Unit Agreement Name                         |
| 2. Name of Operator<br>Pogo Producing Company                                                                                                                                                             | 8. Farm or Lease Name<br>State L-922           |
| 3. Address of Operator<br>P.O. Box 10340 Midland, Texas 79702                                                                                                                                             | 9. Well No.<br>2                               |
| 4. Location of Well<br>UNIT LETTER <u>J</u> <u>1780</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM<br>THE <u>East</u> LINE, SECTION <u>28</u> TOWNSHIP <u>21-S</u> RANGE <u>34-E</u> NMPM. | 10. Field and Pool, or Wildcat<br>Undesignated |
| 15. Elevation (Show whether DF, RT, GR, etc.)<br>3726' GR, 3743' KB                                                                                                                                       | 12. County<br>Lea                              |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|                                                |                                                                    |                                                     |                                               |
|------------------------------------------------|--------------------------------------------------------------------|-----------------------------------------------------|-----------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/>               | REMEDIAL WORK <input type="checkbox"/>              | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>                              | COMMENCE DRILLING OPS. <input type="checkbox"/>     | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <u>Plug Bone Springs &amp; well</u> <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> |                                               |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 9000', cap w/35' cement.
  2. Spot 100' cmt, 5700' to 5600'
  3. Spot 100' cmt, 3700' to 3600'
  4. Perf 4 shots @ 1800'. Squeeze 450 sxs to allow 100' cmt between 9 5/8" & 7" and leave 100' cmt in 7" csg from 1800' to 1700'
  5. Spot 10 sxs @ surface, cutoff csg, weld on plate & install marker
- Procedure established by Eddie Seay 2/24/86

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

|                                 |                                 |                          |
|---------------------------------|---------------------------------|--------------------------|
| SIGNED <u>[Signature]</u>       | TITLE <u>Petroleum Engineer</u> | DATE <u>2/24/86</u>      |
| ORIGINAL SIGNED BY JERRY SEXTON | DISTRICT 1 SUPERVISOR           | DATE <u>MAR 3 - 1986</u> |