

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-26318
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name LLano "34" State
Well No. 1
Pool name or Wildcat Grama Ridge Morrow; East

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			
Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>			
Name of Operator Nearburg Producing Company			
Address of Operator 3300 North "A" Street, Building 2, Suite 120, Midland, TX 79705			
Well Location Unit Letter I 1650 Feet From The South Line and 660 Feet From The East Line Section 34 Township 21S Range 34E NMPM Lea County			
Elevation (Show whether DF, RKB, RT, GR, etc.) 3651' GR			

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Nearburg Producing Company requests to Plug and Abandon the above referenced well as follows:

- 1.) Set CIBP @ 12,750'. Cap w/ 35' of cement. Circ w/ mud. TAG
- 2.) Set 100' plug f/ 11,650' to 11,550'. (Top of Strawn 11,626')
- 3.) Set 100' plug f/ 8400' to 8300'. (Top of Bone Spring 8348')
- 4.) Set 100' plug f/ 5450' to 5550'. (Top of Delaware Sd 5498')
- 5.) Cut 7-5/8" csg @ 5000' and pull.
- 6.) Spot 100' plug f/ 50' to 50' out of csg stub. TAG
- 7.) Spot 100' plug f/ 4000' to 4100'. (Top of Yates 4104')
- 8.) Spot 100' plug f/ 1150' to 1250'. (Base surface csg 1200') TAG
- 9.) Set 30' surface plug & cry hole marker.

TERMINATE E/2, SECTION 34, 320 ACRE SPACING UNIT.

THIS NOTICE MUST BE NOTIFIED 30 DAYS BEFORE THE BEGINNING OF THE PLUGGING OPERATIONS FOR THE CIBP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kim Stewart TITLE Regulatory Analyst DATE 11-19-2001

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY Harry W. Wink TITLE

DATE 11-19-2001

CONDITIONS OF APPROVAL, IF ANY:

3

mp