ENERGY AND MINERALS DEPARTME	nt	
we, or cories acceived	OII CONSERVATION DIVISION	1
DISTRIBUTION	P. O. BOX 2088	Farm C-103
SANTA FE	<b>1</b>	Revised 10-1-78
FILE	SANTA FE, NEW MEXICO 87501	
U.S.O.S.	†	5a. Indicate Type of Lease
LAND OFFICE		State X Fue
OPERATOR	1	5. State Oil & Gas Lease No.
<u> </u>		B-935
SUNDR	RY NOTICES AND REPORTS ON WELLS  PROSALS TO CRILL OF TO DECIPIN ON PLUG BACK TO A DIFFERENT RESERV  TOR FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	OIR.
OIL SAB WELL SAB	OTHER-	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Evyon Cornorat	ion	New Mexico "G" State
Exxon Corporat: 3. Address of Operator	LOH	9. Well No.
	widle. I m	3, Well 110.
	, Midland, Texas 79702	20
4. Location of Weil		10. Field and Poel, or Wildcat
UNIT LETTER	660 FEET FROM THE SOUTH LINE AND 660	FEET FROM Eumont Oil
THE West LINE, SECTION		нмрм.
	15. Elevation (Show whether DF, RT, GR, etc.) 3574	12. County
Check	Appropriate Box To Indicate Nature of Notice, Rep	port or Other Data
		BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	
77		ALTERING CASING
TEMPORARILY ABAHDON	COMMENCE DRILLING OPHS.	PLUG AND ABAROGNMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT	
	OTHER Plug E	Back X
ОТИСЯ		
17. Describe Proposed or Completed Opwork) SEE RULE 1103.	perations (Clearly state all pertinent details, and give pertinent date	es, including estimated date of starting any proposed
l. Plug set by on top.	y Schlumberger thru 2" tubing on WI	, at 3860' with 2' cement
2. Tag cement	at 3860', dumped 6' cement on top	of plug.
3. Well ready	to be placed on production.	

	•	•	·	
eby certify that the information abo				