STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	1
POITURIBLEID	1
SANTA PE	
FILE	
U.S.O.S.	
LAND OFFICE	
DPERATOR	

"CNOITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103

SANTA FE, NEW MEXICO 87501	Revised 10-1-78
· ·	Sa. Indicate Type of Lette
U.S.O.S.	State X Fro
OPERATOR	S. State Off & Gas Lease No.
	F-218
SUNDRY NOTICES AND REPORTS ON WELLS	
USC MAPPICICATION FOR PERMIT - " (FORM CHIST) FOR SUCH PROPOSALS.)	
OIL X GAS OTHER-	7, Unit Agreement Name
2. Name of Operator	8. Form or Lease Name
AMOCO PRODUCTION COMPANY	State C Tract 11
J. Address of Operator	9. Well No.
P. O. Box 68, Hobbs, NM 88240	11
	10. Flede and Pool, or Wildeat
UNIT LETTER X 510 FEET FROM THE SOUTH LINE AND 560 FEET FROM	**************************************
THE East LINE, SECTION 2 TOWNSHIP 21-S FANCE 36-E NAMED	/*************************************
THE LINE, SECTION TOWNSHIP PANCE NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3523.9' GC	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Ot	her Data
NOTICE OF INTENTION TO: SUBSEQUEN	REPORT OF:
PERFORM REMEDIAL WORK	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	PLUC AND ABANDONMENT
other downhole commi	ngle
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any property
Work) SEE RULE 1103.	commerce date of starting any proposed
Moved in service unit 9-23-83. Pulled rods and rods parted. Pumped 3	
BOP. Pull out parallel anchor. Worked stuck shoe loose and milled ba	
fish at 6655'. Unable to work loose and unable to release spear. Ran	
at 6481'. Jar on spear and work loose. Broke circulation mill from 66 to 6660' and mill to 6661' and fell through. Push to 6825'. Milled t	
Latch in fish at 6654' and jar for 7 hours. Unable to release spear a	, 5
6653'. Ran tubing and tagged at 6654'. Load well with 300 bbl brine	2% KCL and milled on
fish 6-1/2 hours, at 6655. Circulated casing clean. Ran tubing and	tagged fish at 6655'.
Load well with 150 bbl 2% KCL BW and broke circulation. Milled on fis	
progress. Tagged fish at 6656' and pumped 80 bbl 2% KCL brine water a	
on fish 6 hours at 6658' and push fish at 6814'. Pulled tubing, drill nothing in shoe. Tagged fish at 6814' and pushed to 6823'. Did not c	
at 6823' and work loose and pulled tubing. Tight spot in casing at 66	
tubing. Released spear. Ran drill collars and tubing to 6800'. Char	
mother hubbard, seating nipple, tubing and tubing anchor. Tubing land	
set at 6609'. Removed BOP and installed tubing flange. Ran rods and	
at 500 psi and OK. Moved out service unit 10-15-83. Start pump testi	
99 BO, 858 BW and 284 MCF in 333 hours. Last 24 hrs. pumped 16 BO, 20 Successful workover to downhole commingle and Blinebry and Drinkard.	DEW, and 32 MCF.
18. ALLENMOCD III. III-IIOH. Ro. Esception Brown L. 15 Me bet Termina Nash in 1001 - 11 Rm: 4.20	06 1-SUSP 1-PJS
1-Petro Lewis	
TITLE Assist. Admin. Analyst	1-18-84
Tittle Mary Miller	DATE 10 CT
ORIGINAL SIGNED BY JERRY SEXTON	
DISTRICT I SUPPRISOR TITLE	JAN 2 0 1984

AN 19 1984