

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTAFE	
FILE	
U.S. U.S.	
LAND OFFICE	
DATE	

OIL CONSERVATION DIVISION

P.O. BOX 2015
SANTA FE, NEW MEXICO 87501

Form O-100
Revised 1-1-78

1. In. Number & Type of Lease
2. Name of Lessee
3. Name of Operator

2-152-3

N.M. "BZ" St. NCT-3

1

Undesignated

Lea

TEXACO Inc.

P.O. Box 728, Hobbs, NM 88240

4. Location of Well
N 730 East from the South 2050

West 26 21-S 34-E

3600' (CR)

Check Appropriate Box(es) if Applicable (See Instructions)
NOTICE OF PRODUCTION TO: SUBSEQUENT REPORTS:

PERFORM REPERFORATION WORK

TESTING OF WELL LOGS

PLUG OR ALTER CASING

PLUG AND ABANDON

CHANGE PLUG

REPERFORATE WELL

CONVERTED TO OTHER USE

CASING TEST AND CEMENT SET

ALTERING CASING

PLUG AND ABANDONMENT

OTHER Proposed completion program

17. Describe the nature of the proposed operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting, and give in block) SEE RULE 1100.

TOTAL DEPTH 13,350'
PLUG BACK TOTAL DEPTH 12,750'

13-3/8" OD 48# H-40 csg set @ 420'
10-3/4" OD 55.5# & 51# H-80 & 45.5# & 40.5# K-55 Csg set @ 5715'
7-5/8" OD 33.7# H-80 Csg set @ 11,020'
4-1/2" OD 15.5# C-75 Csg set @ 13,350'

1. Packer set @ 12,350'. Set CISP @ 12,300'. Spot 50' cement on top of plug.
2. Set 100' cement plug from 10,920'-10,820'.
3. Perforate 7-5/8" csg w/2 JSPF from 8760'-8766', 8771'-8788', & 8979'-8992'.
4. Set RBP @ 9020' & pkr. @ 8940'. Acidize & test as required.
5. Place on production if successful.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: [Signature] TITLE: Asst. Dist. Supt. DATE: 7-21-82

Orig. Signed by
John [Name]

APPROVED BY: [Signature] TITLE: DATE:

CONDITION OF APPROVAL, IF ANY: