

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.M.	
LAND OFFICE	
OPERATOR	

U. S. CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL HITS DEEPER OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PLUG BACK (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	5a. Indicate Type of Lease State ☒ Fee ☐
2. Name of Operator ERNIE L. HEGWER, INC.	5. State Oil & Gas Lease No. E-1639
3. Address of Operator P. O. BOX 24 HOBBS, NEW MEXICO 88240	7. Unit Agreement Name C
4. Location of Well UNIT LETTER C 660 FEET FROM THE NORTH LINE AND 1980 FEET FROM THE WEST LINE, SECTION 11 TOWNSHIP 21 SOUTH RANGE 35 EAST N.M.P.M.	8. Farm or Lease Name ENDURA
	9. Well No. #2
	10. Field and Pool, or WHdcut EUMONT
15. Elevation (Show whether DF, FT, GR, etc.)	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Perforate 1 shot per foot: 3849, 50, 52, 54, 56, 60, 65. 3910, 12, 14, 16, 20
22, 24, 40, 42, 46, 50, 59, 60. Acidize with 3,000 gallons 15% WCA acid.
Swab test. Fracture test with 40,000 gallons (20,000 gel water) (20,000 CO2).

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ernie L. Hegwer TITLE PRESIDENT DATE 3/10/80
Orig. Signed by
APPROVED BY John Runyan TITLE _____ DATE _____
Geologist
CONDITIONS OF APPROVAL, IF ANY:

MAR 12 1980