

PROCEDURE - Continued
EAVES LEA STATE UNIT WELL NO. 1
Eaves Prospect
Lea County, New Mexico

Page 2

10. RIH w/tbg to 50' inside csg cut-off.
11. Set 75 sxs plug.
12. If csg cut off below 10,000': Spot 55 sxs cmt plug @ 10,050'.
13. If csg cut off below 9000': Spot 55 sxs cmt plug @ 9035'.
14. Pick up & spot 80 sxs plug @ 5462'.
15. Pick up & spot 75 sxs plug @ 1575'.
16. POOH & spot 10 sxs @ surface.
17. RD csg puller.
18. Weld on $\frac{1}{2}$ " plate & 4' P&A marker.
19. Clean up location.

MIDLAND DISTRICT DRILLING DEPARTMENT:
2-9-82 JRH:ESP:1b