Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

**DISTRICT I** 

OIL CONSERVATION DIVISION

Revised 1-1-89

P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088	WELL API NO. 30-025-27306
DISTRICT II P.O. Drawer DD, Artesia, NM \$8210  Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	STATE X FEE  6. State Oil & Gas Lesse No. E-1924
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
1. Type of Well: OR GAS WELL OTHER	San Simon 32A St. Com
2. Name of Operator Phillips Petroleum Company	8. Well No.
3. Address of Operator 4001 Penbrook Street, Odessa, TX 79762	9. Pool name or Wildcat East Grama Ridge Morrow
4. Well Location  Unit Letter N : 660 Feet From The South Line and 1980	Sen Simon Wolfcamp  Rest From The West Line
Section 32 Township 21-S Range 35-E	NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3641.5' GR	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN	G OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND C	EMENT JOB
	Wolfcamp & Morrow Zones & X
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give persinent dates, including estimated date of starting any proposed work) SEE RULE 1103.	
03-17-93 - Try to release seal assembly. Rotate & work pipe. RU rotary wireline	
& freepoint. Stuck at seal assembly 10,800'. Cut tbg. 10,764'. POOH w/200 jts. 2-7/8" prod. tbg.	
03-18-93 - POOH w/136 jts. 2-7/8". GIH w/overshot, bumper sub, accelerator, 6-	
3-1/2" DCS & 196 jts. 2-7/8" L-80 workstring. 03-19-93 - PU 150 jts. 2-7/8" L-80 workstring. Latch onto fish 10,764'. Jar fish	
loose. POOH & LD fishing tools, 6 3-1/2" DCS. Fish & 45 jts. 2-7/8" 6.5 Vam Tbg.	
03-20-93 - RU & run gauge ring to 12,700' & stop. POOH & TIH w/bars & CCL & stop	
@12,768'. 03-21-93 - POOH & LD 230 jts. 2-7/8" workstring.	
03-23-93 - POOH & LD 170 jts. 2-7/8" workstring. GIH w/2-7/8" WS and pkr. Test	
to 9000 psi. Found two splits. LD 2 jts 2-	7/8" 6.5 N-Loc.
I hereby certify that the information above is frue and complete to the best of my knowledge and belief.	
SIGNATURE Supv. Regulatory Affairs DATE 10-06-93	
TYPEOR PENT NAME /L. M. Sanders	1915) 368-1488
(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON	
DISTRICT I SUPERVISOR	NCT 1 9 1993

This Approval of Temporary
Abandonment Expires