

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-27306
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-1924
7. Lease Name or Unit Agreement Name San Simon 32 A St. Com.
8. Well No. 1
9. Pool name or Wildcat San Simon Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator Phillips Petroleum Company
3. Address of Operator 4001 Penbrook St., Odessa, Texas 79762
4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>32</u> Township <u>21-S</u> Range <u>35-E</u> NMPM <u>Lea</u> County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3641.5' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MI DDU. NU BOP. GIH with 2-3/8" workstring to PBTD 11,110'.
2. Spot plug no. 1 (40 sx cement) 10,753'-11,110'.
3. Spot plug no. 2 (25 sx cement) 8,108'-8,208'.
4. Freepoint the 7" casing. Need to cut and pull at 5750'.
5. Spot plug no. 3 (80 sx cement) 5,650'-5,800'. WOC and tag.
6. Spot plug no. 4 (40 sx cement) 2,262'-2,362'.
7. Spot plug no. 5 (20 sx cement) 3'-50'.
8. Cut off casing 3' below GL. Install monument marker and perform reclamation work.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Supervisor, Reg. Affairs DATE 3/18/94

TYPE OR PRINT NAME L. M. Sanders TELEPHONE NO. 915/368-1488

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE APR 11 1994

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 22 1994

**RECORDS
OFFICE**