

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
reverse side)

E
re

Budget Bureau No. 1004-0130
Expires August 31, 1985
LEASE DESIGNATION AND SERIAL NO.

NM61608

IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
TEXAKOMA OIL & GAS CORPORATION
3. ADDRESS OF OPERATOR
12801 N. Central Expwy., Suite 250, Dallas, TX 75243
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
3329' FNL & 760' FEL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Lea County Prospect

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT
Lea County Prospect GB
San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

5-21S-37E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3478.6' GL

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent
to this work.)*

- 7/18 - Spot 20 sacks Class C @3906'.
7/19 - GIH to 3906', no plug. Spot 30 sacks Class C w/2% CLC. WOC 4 hrs. GIH to 3906'
no plug. Spot 30 sacks Class C @3906'. POH
7/20 - GIH with tubing, tag plug @ 3776'. Circ hole with 9.5# mud. POH. Spot 15 sacks
from 2708' - 2549'. POH to 1472', mix 20 sacks from 1472' - 1260'. POH to 279'.
Mix 25 sacks from 279' - 170'. POH.
7/21 GIH tag plug @ 184'. POH. Mix 10 sacks @ surf. Install DHM. RDMO.

Aug 17 1 10 PM '88
CASA
AREA

RECEIVED

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent

DATE

08-11-88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

8-25-88

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side