

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1.

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒	GAS WELL ☐	OTHER ☐	7. Unit Agreement Name Eunice Monument South Unit
Name of Operator Chevron U.S.A. Inc.			8. Farm or Lease Name
Address of Operator P.O. Box 670 Hobbs, NM 88240			9. Well No. 345
Location of Well UNIT LETTER 0 760 FEET FROM THE South LINE AND 1880 FEET FROM THE East LINE, SECTION 10 TOWNSHIP 21S RANGE 36E NMPM.			10. Field and Pool, or Wildcat Eunice Monument G/SA
15. Elevation (Show whether DF, RT, GR, etc.) 3567.4' GL			12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
WILL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☒	OTHER completion ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

ND WH & NU BOP, PU WS to 4019'. Circ. hole and displace. Log w/ CNL, CCL and GR, from TD to 3000'. Perf w/4" guns. 1 JHPF, phased 120°, 10 holes, in zone 5, at 3952-62, acidize with 1000 gallons 15% NEFE HCL. Swab (21BW, no oil). GIH w/cmt retainer to 3940'. Sqz perfs 3952-62 w/200sx Class C, displace w/CKF. Obtained running squeeze, reverse out 70 sx, RU to perf w/ 4" guns. 1 JHPF, 180° phased, 88 holes, in zone 1-4 at 3768-74, 3782-90, 3796-3802, 3810-34, 3844-72, 3906-22, Acidize with 6500 gallons 15% NEFE HCL, swab. Run production tubing (2 3/8" to 3917'), run pmp. equip. Space out, ck pmp action, ok. Turn over to production. 9-17-87 through 9-22-87

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

by M. E. Abbin TITLE Staff Drilling Engineer DATE Sept. 24, 1987

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

COPIES BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

SEP 28 1987

RECEIVED

SEP 25 1987

**GCD
HOBBS OFFICE**