

STATE OF NEW MEXICO
OIL AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒	GAS WELL ☐	OTHER ☐	7. Unit Agreement Name Eunice Monument South
Name of Operator Chevron U.S.A. Inc.			8. Farm or Lease Name Unit
Address of Operator P.O. Box 670 Hobbs, NM 88240			9. Well No. 219
Location of Well			10. Field and Pool, or Wildcat Eunice Monument South
UNIT LETTER <u>L</u> <u>3222</u> FEET FROM THE <u>North</u> LINE AND <u>781</u> FEET FROM THE <u>West</u> LINE, SECTION <u>6</u> TOWNSHIP <u>21S</u> RANGE <u>36E</u> N.M.P.M.			11. County Lea
15. Elevation (Show whether DF, RT, GR, etc.) 3554.5'			

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

FORM REMEDIAL WORK ☐
PARTIALLY ABANDON ☐
OR ALTER CASING ☐
THIR ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPER. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER completion ☒

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
TD: 4252 PB: 3955

Run GR,CCL,CBL. Perf 4020-4038, 3986-4000, w/4" guns, 1SPF, 180° phase. Acidize w/1600 gallons 15% NEFE. Swab test. Set CIGR at 3965'. Sqz perfs 4038-3986 w/200sx C1 C. Rev. out 72sx cmt. 128 sx below CIGR. Perf 3896-3906 & 3924-3934 (20 holes), 1 SPF, 180° phase, 4" guns. Acidz w/1000 gal 15% NEFE. Swab. Perf 3843-54, 3864-76 (23 holes) 4" guns, 1SPF. Acidz w/1100 gal 15% NEFE. Displace w/ CKF. Swab. Set 5½" CIGR at 3721', sqz perf in zone 1 3843-3876 w/250sx C1 C. Displ w/ FW. Rev out 91sx to surf. Left 13 sx in csg. WOC 24 hrs. Drlg out cmt and circ. clean. Perf w/4" guns 1 SPF, 180°, 16 holes, f/3738-3754, acidize w/900 gal 15% NEFE HCL. Swab. DO CIBP at 3886. Push down hole to 3955. Circ clean. RIH w/2 7/8" prod. tbq. EOT at 3937, SN 3900', TAC at 3620'. Space out, load and test to 500psi. Test pmp action, ok. Clean location. RD PU. Turn over to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

M. E. Abin TITLE Staff Drilling Engr. DATE August 2, 1988
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR
DATE AUG 15 '88
CONDITIONS OF APPROVAL, IF ANY: