

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30511
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. N/A
7. Lease Name or Unit Agreement Name EUNICE MONUMENT SOUTH UNIT
8. Well No. 620
9. Pool name or Wildcat EUNICE MONUMENT G ¹ /sa

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator CHEVRON U.S.A. INC.
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	4. Well Location Unit Letter R : 2360 Feet From The SOUTH Line and 1330 Feet From The EAST Line Section 6 Township 21S Range 36E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3574 GE	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: ACDZ <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU, POOH WITH PRODUCTION EQUIP.
TRIP IN HOLE WITH BIT AND TAG AT BTM OF HOLE, 3962'.
SWAB TEST, ACDZ HOLE ZINES 2-4 WITH 3000 GALS. OF 28% NEFE AND 30 TONS OF CO2. FLOW WELL BACK. SWAB TEST ZONES 2-4.
TIH WITH PRODUCTION EQUIP. AND RETURN TO PRODUCTION.
WORK STARTED 2-13-92 ENDED ON 2-14-92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE P.R. Matthews TITLE TECHNICAL ASSISTANT DATE 2-17-92
TYPE OR PRINT NAME P.R. MATTHEWS TELEPHONE NO. 687-7812

(This space for State Use)

Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE FEB 2 1992
CONDITIONS OF APPROVAL, IF ANY: _____