

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-30577</u>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <u>J. A. Akins</u>
8. Well No. <u>17</u>
9. Pool name or Wildcat <u>Hardy Tubb Drinkard</u>

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator <u>ORIX ENERGY COMPANY</u>	
3. Address of Operator <u>P.O. Box 2880 Dallas TX 75221-2880</u>	
4. Well Location Unit Letter <u>T</u> <u>2260</u> Feet From The <u>South</u> Line and <u>800</u> Feet From The <u>West</u> Line Section <u>3</u> Township <u>21S</u> Range <u>36E</u> NMMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3566' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-18-91 MIRU WS RIG, PULLED RODS, CLEANING UP WELL
2-19 to 2-23-92 CLEANING AND SCRAPING OUT WELL
2-24-92 ACIDIZE DRINKARD PERFS 6585-6806' W/ 2000 GAL 15% NEFEHCL
W/ 400 SCF/BBL N2
2-25 thru 2-26-92 SWABBING WELL
2-27 to 3-12-92 WELL PUT ON PRODUCTION AND TESTING
3-12-92 WELL TEST, 24HRS, P 43 BO, 120 BW, 70 MCF AFTER WORKOVER
BEFORE WORKOVER 19 BO, 15 BW, 55 MCF

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE EWELL SCHIRMER TITLE Professional Geologist Rep DATE 5-22-92
TYPE OR PRINT NAME EWELL SCHIRMER TELEPHONE NO. 715-3550

(This space for State Use)
Orig. Signed by Paul Kautz
Geologist
APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

JUN 01 '92