Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N.M. Oil Care P.O. Box 1950

FORM APPROVED Hobbs, NM 88241 Budget Bureau No. 1004-0135

SUNDRY NOTICES AND REPORTS ON WELLS		Expires. March 31, 1993
		5. Lease Designation and Serial No. NM-86710
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals		6. If Indian, Alottee or Tribe Name
		7. If Unit or CA, Agreement Designation
1 Type of Well: OIL GAS	П	8. Well Name and Number BILBREY 33 FEDERAL
WELL WELL	OTHER	1
TEXACO EXPLORATION & PRODUCTION INC.		9. API Well No.
3. Address and Telephone No. 205 E. Bender, HOBBS, NM 88240 397-0405		30-025-30781
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Feet From The NORTH Line and 1980 Feet From The		10. Field and Pool, Exploaratory Area BILBREY ATOKA, NORTH (GAS)
Unit Letter C: 660 Feet From The NORTH Line and 1980 Feet From The		11. County or Parish, State
WEST Line Section 33	Township 21S Range 32E	LEA , NEW MEXICO
12. Check Appropriate	Box(s) To Indicate Nature of Notice, R	eport, or Other Data
TYPE OF SUBMISSION	T	YPE OF ACTION
	Abandonment	☐ Change of Plans ☐ New Construction
☐ Notice of Intent	Recompletion Plugging Back	☐ Non-Routine Fracturing
_	Casing Repair	☐ Water Shut-Off
Subsequent Report	Atlering Casing	Conversion to Injection
Final Abandonment Notice	OTHER: Recomp was unsucc	
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)
 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*. 4-12-99: MIRU. TIH W/PROF PLUG. ATTEMPT TO SET @ 13,921'. PLUG DID NOT SET. RUN 2ND PLUG. SET @ 13,921'. 4-13-99: HYDROSTATIC HEAD OF 10# BRINE IS 7230 PSI @ 13,921'. WILL PULL PROF PLUG & SET CIBP IN TP. 4-14-99: TIH TO FISH PROF PLUG. LATCH PLUG & EQUALIZE PSI. CAME UP HLE @ 30' & STUCK. DROP 2ND CUTTER CUT LINE. PU FSH TOOL. 4-15-99: TIH W/CIBP. TAG @ 13,812. PU 1'. SET CIBP @ 13,811'. LOAD W/60 BBLS BRINE & TEST CIBP TO 1000 PSI. ND TREE. NU 10-K TREE. TEST BOP & CHOKE MANIFOLD. TIH W/CHEM CUTTER. TAG @ 13,811'. CUT TBG @ 13,806'. DISPL 10# BRINE W/FRESH 2% KCL W/PKR FLUID. 4-16-99: OPEN WELL. WELLCHECK 2 3/8" TBG OUT OF HLE. 4-17-99: TIH W/RWRP ON 9TH TRY WENT THRU LINER TOP @ 11,674'. PLUG STPD @ 11,954'. SET WRP @ 11,954'. TIH W/RETR TOOL. 4-19-99: TIH W/NEW BIT. TAG TOP OF FISH @ 13,788'. TIH W/BIT & CSG SCRAPER TO 11,630'. 4-22-99: TIH TO 13,375'. TIH W/RBP. STUCK @ 11,942'. SET PLUG. TIH TO 11,942'. LATCH RBP & REL. LOWER RBP TO 11,974'. 4-23-99: TIH TO 13,375'. TIH W/RBP. STUCK @ 11,942'. SET RBP @ 13,750'. TEST TO 500 PSI-OK. 4-24-99: TIH W/DUB BAILER. TAG RBP @ 13,750'. SET RBP @ 13,750'. TEST TO 500 PSI-OK. 4-24-99: TIH W/DUB BAILER. TAG RBP @ 13,750'. DUMP 10' ON RBP. TIH W/REF-ENTRY SUB, PKR. TEST TBG TO 800#. TIH TO 13,642'. 4-26-99: TIH W/DUB BAILER. TAG RBP @ 13,750'. SET RBP @ 13,750'. TEST TO 500 PSI-OK. 4-28-99: TEST LUBRICATOR TO 4000#-OK. 4-28-99: TEST LUBRICATOR TO 4000#-OK. TIH W/GAUGE RING. TAG SD @ 13,733'. TIH W/GUN ON WL & PERF LINER IN ATOKA FORM @ 13,630-37'. RU SWAB. FL @ SURF. END FL @ 10,000'. 4-29-99: FL @ 10,500'.		
14. I hereby certify that the foregoing in true and correct SIGNATURE A MUMISU NE	ark TITLE Engineering Assistant	DATE6/3/99
TYPE OR PRINT NAME J. Den	ise Leake	
(This space for Federal or State office use)	Chang TITHORIG SGD.) DAVID A. C	LASS JUL 21 1999
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	1911N Z W 17994	RVISUR
Title 18 LLS C. Section 1001, makes it a crime for any person	in knowingly and willfully to make to any department or agency of the U	nted States any false, fictitious of fraudulent statements or
representations as to any matter within its jurisdiction.		J