

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30904
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. New
7. Lease Name or Unit Agreement Name Wilson State
8. Well No. 1
9. Pool name or Wildcat Wilson Yates - SR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Stevens & Tull, Inc.	
3. Address of Operator P.O. Box 11005, Midland, Texas 79702	
4. Well Location Unit Letter <u>D</u> : <u>990</u> Feet From The <u>North</u> Line and <u>990</u> Feet From The <u>West</u> Line Section <u>11</u> Township <u>21-S</u> Range <u>34-E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3696.3 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Drill 12 1/4" hole to 1394' - good anhydrite casing seat
- 2) Set 8 5/8" casing to 1394'
- 3) Cemented w/500 sacks "C" w/4% gel, 2% CaCl<sub>2</sub>, 1/4#/sack cellophane, 100 sacks "C" w/2% CaCl<sub>2</sub>, 1/4# cellophane. Circulated 75 sx.
- 4) Wait on Cement 12 hours.
- 5) Test BOP to 1000 psi for 30 minutes.
- 6) Drill to TD of 4040 with brine mud.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rodney L. Seale TITLE Engineer DATE 6/12/90  
TYPE OR PRINT NAME Rodney L. Seale TELEPHONE NO. 699-1410

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

JUN 21 1990

RECEIVED

JUN 20 1990

OCD  
HOBBS OFFICE