

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31336
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1398
7. Lease Name or Unit Agreement Name SHELL E STATE COM
8. Well No. 3
9. Pool name or Wildcat EUMONT-YATES-7RIVERS-QUEEN
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3553.2'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER DRY HOLE <input type="checkbox"/>
2. Name of Operator MERIDIAN OIL INC.
3. Address of Operator P.O. Box 51810, Midland, TX 79710-1810
4. Well Location Unit Letter L : 3500 Feet From The NORTH Line and 690 Feet From The WEST Line Section 6 Township 21-S Range 36-E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3553.2'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NOTIFY OCD PRIOR TO COMMENCING PLUGGING OPERATIONS.

BAIL 35' OF CMT ON TOP OF CIBP AT 3400'. SET CIBP AT 2990' AND BAIL 35' CEMENT ON TOP. SET CIBP AT 2750'. SET CMT PLUG ACROSS THE BASE OF THE SALT AT 2535' TO 2750' WITH 15 SXS CLASS C CEMENT, 2% CACL2. LOAD HOLE WITH GELLED 9 PPG BRINE. SET CEMENT PLUG ACROSS THE TOP OF THE SALT AT 1440' TO 1560'. USE 10 SXS CLASS C CEMENT, 2% CACL2. PULL UP TO 480' AND CIRCULATE CEMENT TO SURFACE. CUT OFF CASING 3' BELOW GROUND LEVEL. INSTALL P&A MARKER. CLEAR AND RESTORE LOCATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Maria L. Perez TITLE PRODUCTION ASST. DATE 3-30-92
TYPE OR PRINT NAME MARIA L. PEREZ TELEPHONE NO. 915-688-6906

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE APR 09 '92
CONDITIONS OF APPROVAL, IF ANY: