

Form 1160
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

FORM APPROVED

Budget Bureau No 1004-0135

Expires March 31, 1993

5 Lease Designation and Serial No

NM85932

6 If Indian Allottee or Tribe Name

7 If Unit or CA Agreement Designation

8 Well Name and No

BW "31" Federal No. 1

9 API Well No

30-025-31394

10 Field and Pool or Exploratory Area

Under Livingston Ridge

11 County or Parish, State

Lea New Mexico

1 Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2 Name of Operator

Collins & Ware, Inc.

3 Address and Telephone No

508 W. Wall, Suite 1200, Midland, Texas 79701 (915) 687-3435

4 Location of Well (Footage, Sec., T., R., M., or Survey Description)

330' FSL & 110' FWL of Section 31, T-21S, R-32E, Unit letter M

12 CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

PLUG AND ABANDONMENT OF BW "31" FEDERAL #1

5-23-94 Set CIBP @ 7120'
5-24-94 Dump 50' cement on top of CIBP
Set CIBP @ 4000'
Dump 50' cement on top of CIBP
RIH & cut off 5 1/2" casing @ 3793'
5-25-94 Pull and LD 89 jts 5 1/2" casing & 2 casing stubs, approximately 3780'
NUWH & BOP
RIH to 3870' and spot 30 sx cement from 3710' to 3870'
5-26-94 Tag cement @ 3713'
Spot 25 sx cement from 750' to 850'
Tag cement @ 746'
Spot 50 sx cement from 65' to surface
Cut off casing and weld on dry hole marker

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

14 I hereby certify that the foregoing is true and correct

Signed

Title

Dianne Sumrall
Production Clerk

Date

6/2/94

(This space for Federal or State office use)

Approved by (ORIG. SGD.) JOE G. LARA

Title

PETROLEUM ENGINEER

Date

7/5/94

Conditions of approval, if any: