

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. 19
P.O. Box 1980
Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
NM-86710

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Luke Federal #2

9. API Well No.

30-025-31442

10. Field and Pool, or Exploratory Area

Lost Tank Delaware

11. County or Parish, State

Lea County, NM

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Pogo Producing Company

3. Address and Telephone No.

P. O. Box 10340, Midland, TX 79702-7340 (915)685-8100

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FNL & 660' FWL, Section 31, T21S, R32E

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other P & A well
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

04/17/98 POOH w/ production equipment. Lay down pump & rods.

04/21/98 Latch onto RBP @ 7412' & POOH.

04/22/98 Set CIBP @ 7021'. Displace well w/ P & A mud.

04/23/98 Cap CIBP w/ 50' (6 sxs) CI "C" cmt plug. Spot 100' (11 sxs) CI "C" cmt plug F/5545'-5445'. Spot 3576' (362 sxs) CI "C" cmt plug F/4392'-4816'. Spot 50' (6 sxs) CI "C" cmt plug F/50' - surface.

04/26/98 Cut off wellhead Weld on cap and P & A marker. Cut off anchors. Clean location. Well P & A'd.

Approved as to plugging of the well bore
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed

Title Senior Operations Engineer

Date 05/06/98

(This space for Federal or State office use)

Approved by

ORIG. SGD LIES RABYAK

Title

PETROLEUM ENGINEER

Date

MAY 15 1998

Conditions of approval, if any:

dp