Ener

Ainerals and Natural Resources Department

District of the	Revised 1-1-89
OIL CONSERVATION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Box 2088	30 025 32562
P.O. Box Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease
DISTRICT III	STATE FEE 🔀
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil / Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name O. LCOLEMAN
1. Type of Weli: OIL GAS WELL OTHER	
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.	8. Well No.
3. Address of Operator 205 E. Bender, HOBBS, NM 88240	9. Pool Name or Wildcat EUMONT YATES 7 RIVERS QUEEN (PRO GAS)
4. Well Location	MOZINO GOZZIN (FINO GAO)
Unit Letter <u>G</u> : 1980 Feet From The <u>NORTH</u> Line and <u>1977</u>	Feet From TheEASTLine
Section 17 Township 21-S Range 36-E NMPM LEA COUNTY	
10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3627'	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPE	
PULL OR ALTER CASING CASING TEST AND CEMEN	
OTHER: OTHER:	
12-15-97: MIRU, INSTL BOP, RAN RETR TOOL ON TBG, RU FOAM UNIT, C/O FRAC SD & BALLS FR 3439-3495'. PULL TO 1000'. 12-16-97: RAN BIT ON TBG, DRILL CIBP FR 3495-3497'. PSH JUNK TO 3723'. LOST CIRC, PULL BIT TO 3070'. 12-17-97: DRILL ON JUNK CIBP FR 3723-3850 (PBTD). 12-18-97: RAN SN & TBG, KILL WELL W/30 BFW, REM BOP, LAND SN @ 3781'. SWAB, 12-19-97: SHUT IN CSG, RDPU, LEFT TBG OPEN TO SALES LINE. 12-22-97: SWAB, RECVD 18 BBLS LOAD. 12-23-97: TURNED DOWN FLOWLINE. 25 PSI FLOWING PRESS @ 352 MCFPD. 12-24-97: 25 PSI @ 300 MCFPD. 12-27 THRU 12-30-97: FLOWING 12-31-97: NO PROD THRU SALES METER, PULL PLUNGER & SPRING, RD SWAB UNIT. 1-02-98: NDWH, PULL & LAY DOWN 2 JTS TBG, SN @ 3719'. NUWH. MONITOR FOR H2S. RU SWAB. FLOWING TO FRAC TANK BUT NOT DOWN SALES LINE. RDMO. 1-05-98: RU SWAB UNIT. SN @ 3719'. DROP PLUNGER & SPRING, GAS RATE OF 460 MCFPD. LEFT ON PLUNGER LIFT. 1-6-98: SWAB. RECVD 0 BO, 7 BW. DROP PLUNGER. LEFT DOWN SALES LINE. 1-08 THRU 1-11-98: SWABBING & FLOWING 1-12-98: WELL DEAD. RD SWAB UNIT. 1-13 THRU 16-98: FLOWING & TESTING 1-19-98: TIH W/GAS ANCHOR ON PUMP, BACKOFF TOOL, SINKER BARS, & RODS. SPACE PUMP @ 1". CLAMP OFF RODS ON TOP OF STUFFING BOX. DID NOT LOAD & TEST TBG, RDPU. 1-28-98: ON 24 HR OPT. PUMPED 0 BO, 10 BW, & 225 MCFD. PUMPING NATURAL GAS. FINAL REPORT	
I hereby certify that the information above is true and complete to the dest of my knowledge and belief. SIGNATURE TITLE Engineering Assistant TYPE OR PRINT NAME J. Denise Leake	DATE <u>2/18/98</u> Telephone No. 397-0405
(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS	MAP DE LA
APPROVED BY DISTRICT SUPERVISOR TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	DeSoto/Nichols 12-93 ver 1.0