

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-33108
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Burlington Resources		6. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 51810, Midland, TX 79710-1810		7. Lease Name or Agreement Name: Platinum State "17"
4. Well Location Unit Letter G : 1,980 feet from the North line and 2,310 feet from the East line Section 17 Township 21-S Range 34-E NMPM County Lea		8. Well No. #1
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,734' KB		9. Pool name or Wildcat Delaware

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

07/10/02 Notified OCD, Buddy Hill. MIRU Triple N rig #25. ND wellhead, NU BOP, POOH w/ packer.

07/11/02 Notified OCD, Buddy Hill. RIH w/ CIBP to 5,875'. RU cementer and set CIBP, circulated hole w/ mud, and pumped 25 sx C cmt 5,875 - 5,505'. POOH w/ tbg and WOC. RIH and tagged cmt @ 5,493'. Perforated casing @ 4,270'. RIH w/ packer and pressured up to 1,500 psi on perforations, no rate. POOH w/ packer and RIH w/ tbg to 4,318'. RU cementer and pumped 25 sx C cmt 4,318 - 3,948'.

07/12/02 Notified OCD, Buddy Hill. Tagged cmt @ 3,950'. Cut and pulled 4 1/2" csg from 2,425'. SDFN.

07/15/02 Cut and pulled 7" casing from 2,421'. NU tubing BOP and RIH w/ tbg to 2,476'. Pumped 65 sx C cmt @ 2,476'. PUH w/ tbg and WOC 2 hrs. RIH and tagged @ 2,490'. Pumped 65 sx C cmt @ 2,476'. POOH w/ tbg and SDFN.

07/16/02 Notified OCD, Buddy Hill. RIH and tagged cmt @ 2,095'. PUH w/ tbg to 575'. Pumped 40 sx C cmt w/ 2% CaCl₂ @ 575'. WOC 3 1/2 hrs and tagged @ 444'. RIH w/ tbg to 60' and pumped 20 sx C cmt 60' to surface.

07/26/02 Cut off wellhead and installed dry hole marker. Cut off anchors and backfilled cellar.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE **Engineer** DATE **07/26/02**

Type or print name **James F. Newman, P.E.** Telephone No. **915-687-1994**

(This space for State use)

APPROVED BY  TITLE **Flt Rep** DATE **8-13-02**

Conditions of approval, if any:

GWW