

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-34144
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-1673
7. Lease Name or Unit Agreement Name STATE 33
8. Well No. 2
9. Pool name or Wildcat GRAMA RIDGE
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3621' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
RAND PAULSON OIL COMPANY, INC.

3. Address of Operator
508 W. WALL, STE 100 MIDLAND, TX 79701

4. Well Location
Unit Letter **F** **1980** Feet From The **NORTH** Line and **2310** Feet From The **WEST** Line
Section **33** Township **21-S** Range **35-E** NMPM **LEA** County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-26-97 DRILL 8 3/4" HOLE TO 11,115'. RAN 7" 23 LBS N-80 & S-95 CASING TO TD. CEMENTED IN 2 STAGES: 250 SX H: POZ 65:35 + 6% GEL + 5% SALT AND TAIL W/ 200 SX CLASS H. 2ND STAGE: 600 SX AS IN STAGE 1. TAIL W/ 200 SX CLASS H. WOC. CUT OFF CSG. NU WELL HEAD & BOP. TEST BOP 4500 PSI + HEAD TO 5000 PSI - OK. INSTALL CHOKE MANIFOLD & TEST TO 5000 PSI - OK. PREP TO DRILL OUT W/ 6 1/8" O.H.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE **O.H. Routh** TITLE **AGENT** DATE **10-28-97**
TYPE OR PRINT NAME **O.H. ROUTH** TELEPHONE NO. **915 687-0323**

(This space for State Use)

APPROVED BY **CHRIS WILLIAMS** TITLE **DISTRICT SUPERVISOR** DATE **NOV 3 1997**

CONDITIONS OF APPROVAL, IF ANY: