

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Geology, Minerals and Natural Resources Department

Form G-10
Revised 1-1-89

DISTRICT I
P.O. Box 180, Hobbs, NM 88240

DISTRICT II
P.O. Drawer 60, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL AP: NO.
30-025-34536

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM G-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
Range 28 State Com.

1. Type of Well: ☒ OIL WELL ☐ GAS WELL ☐ OTHER Dry Hole

2. Name of Operator
Nearburg Producing Company

8. Well No.

1

3. Address of Operator
PO Box 823085, Dallas Texas 75382-3085

9. Port Name or Wellbore
Gram Ridge Morrow East

4. Well Location
Well Letter G 1980 Feet From Top North Line 1650 Feet From Top East Line

Section 28 Township 21S Range 35E NMPM Lee County
10. Elevation (Show whether OP, RGS, RT, GR, etc.)
3591 Gr.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: **SUBSEQUENT REPORT OF**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPERATIONS ☐ PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐ CASING TEST AND CEMENT JOB ☐
OTHER ☐ OTHER ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed
work.) SEE RULE 1107.

3/31/99 LOAD HOLE WITH BRINE BASED MUD, SPOT 25 SX'S "H" CMT ON BP SET AT 10,500'
3/31/99 SET CIBPE 10,150' CAP WITH 35' CMT. (DUMP BAILER)
3/31/99 SET CIBPE 7734' CAP WITH 35' CMT. (DUMP BAILER)
4/1/99 CUT AND PULL 7" CASING AT 6140'
4/2/99 SPOT 75 SX'S "C" CMT @ 6190' WOC TAG @ 5987'
4/2/99 SPOT 75 SX'S "C" CMT @ 5620' (9 5/8 SHOE @ 5570') WOC
4/5/99 TAG CMT TOP AT 5508', SPOT 75 SX'S "C" CMT @ 3600'-3500'
4/5/99 ~~SPOT~~ SPOT 75 SX'S "C" CMT @ 1400'-1300' (13 3/8 SHOE @ 1350')
4/5/99 SPOT 10 SX'S "C" CMT 10'-SURF SET DRY HOLE MARKER
REMOVE DEADMEN, BACK FILL CELLAR & WORKPIT CLEAN LOC.

"H" CMT - 15.6 PPG 1.18 YIELD "C" CMT - 14.8 PPG 1.32 YIELD MUD - 25# P/88L BRINE

(I hereby certify that the information herein is true and correct to the best of my knowledge and belief)

SIGNATURE: Poly Abalos TITLE: President DATE: 4/5/99
TYPE OR PRINT NAME: POLY ABALOS TELEPHONE NO.: 915/520 12018

(This space for State Use)

APPROVED BY: [Signature] TITLE: Asst. Reg. DATE: 1-30-03
CONDITIONS OF APPROVAL, IF ANY:
GWW