

**DISTRICT I**

P.O. Box 1980, Hobbs, NM 88240

**DISTRICT II**

P.O. Box Drawer DD, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-35168	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name EUNICE MONUMENT SOUTH UNIT	
8. Well No. 750	
9. Pool Name or Wildcat GRAYBURG SAN ANDRES	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3567' GL	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>
2. Name of Operator	CHEVRON USA INC		
3. Address of Operator	15 SMITH ROAD, MIDLAND, TX 79705		
4. Well Location	Unit Letter <u>H</u> : <u>1420</u> Feet From The <u>NORTH</u> Line and <u>200'</u> Feet From The <u>EAST</u> Line Section <u>16</u> Township <u>21-S</u> Range <u>36-E</u> NMPM <u>LEA</u> COUNTY		
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
 PULL OR ALTER CASING ☐  
 OTHER: PERF & ACIDIZE ☒

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
 COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
 CASING TEST AND CEMENT JOB ☐  
 OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CHEVRON U.S.A. INTENDS TO CLEAN OUT, PERF, & ACIDIZE THE SUBJECT WELL.

- 1) VERIFY ANCHORS HAVE BEEN SET & TESTED.
- 2) MIRU PU. NDWH. NUBOP.
- 3) TOH W/PMP & TBG.
- 4) TIH W/BIT & CSG SCRAPER TO PBTD @ 3936. CIRC CLN.
- 5) RU WL. PERF 3802-10, 3814-24.
- 5) TIH W/PKR & RBP TO 3912.
- 6) ACIDIZE PERS W/7000 GALS 15% HCL.  

PACKER	PERFS	ACID
3912'	3914-30'	1000 GALS
3886'	3890-3904'	1000 GALS
3854'	3860-77'	1000 GALS
3826'	3828-50'	1500 GALS
3800'	3802-24'	2500 GALS
- 7) RUN PACKER BACK TO 3700'. SWAB BACK SPENT ACID.
- 8) TIH W/PRODUCTION TBG & PMPNG EQPT.
- 9) NDBOP. NUWH. RDP.
- 10) PLACE WELL BACK ON PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Leake TITLE Regulatory Specialist DATE 7/3/2002  
 TYPE OR PRINT NAME Denise Leake Telephone No. 915-687-7375

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ORIGINAL SIGNED BY  
 GARY W. WINK  
 OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

JUL 9 2002  
 DeSoto/Nichols 12-93 ver 1.1

5  
C