


OIL CONSERVATION COMMIC SANTA Fo, New Mexico



Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten specified is completed. It should be signed and sworn to before a notary public for reports on backling.

ations, results of shooting well, results of even though the work was witnessed by a and sworn to before a notary public. Se	test of casing in agent of the	shut-off, Commis	result of plugging of sion. Reports on a	f well, and other im	portant	operations,
			by checking below:	negulations of the	Commis	3S10N.
REPORT ON BEGINNING DRILLING OPERA-			REPORT ON REPAIRING WELL			
EPORT ON RESULT OF SHOOTING OR CHEM- ICAL TREATMENT OF WELL			REPORT ON PULLING OR OTHERWISE ALTERING CASING			
REPORT ON RESULT OF TEST OF CASING SHUT-OFF			REPORT ON DEEPENING WELL			
REPORT ON RESULT OF PLUGGING	OF WELL	x				
		Midl	and, Texas,	September		1946
OIL CONSERVATION COMMISSION, SANTA FE, NEW MEXICO. Gentlemen: Following is a report on the work done and the same of the same	nd the results	obtained	under the heading			
The Texas Company's Stat		7	Lease 01	Well No. 1		
NW# SE# of	Sec. 28 /	, T.	17-8 //	R. 34-R	N	. M. P. M.,
Vacuum Fie	,		Teg .			County.
The dates of this work were as follows: Notice of intention to do the work was (v						
As indicated on our Form with your office August in the following manner:	24, 1945					
	Please s	ee re	verse side)			
Vitnessed byNa	ıme		Company			Pitle
Subscribed and sworn before me this_	<u> </u>	I he	ereby swear or affir	m that the inform	ation g	iven aboye
27th day of September	, 19 4	6 Nan				Cabanesa
Elizaber For & Bliza	beth Frv	Posi	tion Drig. 8	Pred. Fore	men	
No	tary Public	Rep	resenting De 1	exas Compar) y	
My commission expires 6-1-47			Com	pany or Operator		
		- Add	ress Box 1270		Texa	
Remarks:	***************************************	_ Add			rexa Lrau	egh.

A cement retainer was set at 3560' and squeezed section below with 100 secks to seeks the pulled with heavy sud. Parted and pulled secks trom 1010 was prosed a cement plug of 30 secks from 1500' to 1540'. (In top of parted 8-5/8" casing and bottom of 10" casing was parted and pulled from 1660'. Spotted a cement plug of 30 secks from approximately 1040' to 930' (in top of parted 10" casing in bottom of 12-1/2" casing). All attempts to parted pull 12-1/2" casing, All attempts to parten parted 10" casing were unsuccessful, and all 18-5/8" casing was left in the hole. The customary 4" pipe marker was comental in the top of the hole. The customary 4" pipe marker was comental in the top of the hole. The customary 4" pipe marker was completed 9-29-45.