

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved
Budget Project No. 42-R1454

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-2" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. LC 063228
2. NAME OF OPERATOR Continental Oil Company	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 460, Hobbs, N. Mex. 88240	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FSL 7330' FWL of sec. 24, T-23S, R-32E Lea County, N. Mex.	8. FARM OR LEASE NAME Field
14. PERMIT NO.	9. WELL NO. 2
15. ELEVATIONS (Show whether OF, RT, GR, etc.)	10. FIELD AND POOL, OR WILDCAT Cruz Delaware
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 24, T-23S, R-32E
	12. COUNTY OR PARISH Lea
	13. STATE N. Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) **Convert to a water disposal well**PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is proposed to convert this well to a salt water disposal well by the following method:

- 1) Spot acid from 5,000' to 5,206
- 2) Perforate from 5,100' to 5,206'.
- 3) Acidize from 5,100' to 5,145' with 2,000 gals of 15% HCL acid.
- 4) Set tubing with packer 5050'.
- 5) Place well on water disposal.

18. I hereby certify that the foregoing is true and correct

SIGNED W. E. YeakleyTITLE Adm. Section ChiefDATE 9-16-68

(This space for Federal or State office use)

APPROVED BY _____

CONDITIONS OF APPROVAL, IF ANY: _____

TITLE _____

APPROVED

SEP 17 1968

J. L. GORDON
ACTING DISTRICT ENGINEER

V. S. G. S. - P FILE *See Instructions on Reverse Side