

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions
reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM-04465

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "WL"

9. WELL NO.

3-~~2~~

10. FIELD AND POOL, OR WILDCAT

Trieste Draw

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 26, T. 23 S., R. 32 E.

12. COUNTY OR PARISH

Lea

13. STATE

N.M.

1. OIL ☒ WELL GAS ☐ WELL OTHER

2. NAME OF OPERATOR

Gene A. Snow

3. ADDRESS OF OPERATOR

606 So 13th Lovington, N.M.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

330 FSL & 660 FEL

Sec. 26, T. 23 S., R. 32 E.

14. PERMIT NO.

15. ELEVATIONS (Show whether of, RT, GR, etc.)

3707.1 G.R.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Plugged well in the following manner:

1. Set C.I. bridge plug @ 5000'.
2. Capped bridge plug with 40' of cement by dump barrel.
3. Fished hole with good mud. Salt gel mixed 1 sack to 4 bbls. brine water.
4. Cut 4" casing @ 2877'. Pulled casing.
5. Set plugs by tubing as follows:
35 lbs @ 2898' to 2798'
" " " 1260' to 1160'
" " " 410' to 310'
10 " " 10' to 0'.
6. Installed regulation marker.

I will notify when location is ready for inspection

18. I hereby certify that the foregoing is true and correct

SIGNED

Gene A. Snow

TITLE

DATE

11-15-72

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE

*See Instructions on Reverse Side

MAY 11 1973
J. L. GORDON
FARM DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.