THE INTERIOR SUBMIT IN TRIPLICATE. (Other instructions of verse side) Form approved. Budget Bureau No. 42-R1424. Form :-331 (May 1963) UNITED STATES 5. LEASE DESIGNATION AND BEBIAL NO. DEPARTMENT 68848 GEOLOGICAL SURVEY IF INDIAN. ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.) 7. UNIT AGREEMENT NAME ī Propose GAS WELL bandonment WELL X OTHER 8. FARM OR LEASE NAME NAME OF OPERATOR 2. OMPM 4 SHALL 88240 LOCATION OF WELL (Report 1 See also space 17 below.) At surface OR WILDCAT with any State requirements.* 10. FIELD A D POOL. 4. Do/oway-4 Z 1980' FSL + 625' FWL OF Soc. 19 SEC., T., B., I OR BLK. SURVEY OR AREA ててころろろ 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO 3701' クト N.M Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16 SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: REPAIRING WELL PULL OR ALTER CASING WATER SHUT-OFF TEST WATER SHUT-OFF ALTERING CASING MULTIPLE COMPLETE FRACTURE TREATMENT FRACTURE TREAT ABANDONMENT⁴ SHOOTING OR ACIDIZING ABANDON SHOOT OR ACIDIZE CHANGE PLANS (Other) REPAIR WELL (NorE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertiproposed work. I nent to this work.) IT IS Proposed To Plug and Abandon The Subject well Bocause of Poor Mochanical Conditions of The Well Bore . Refer to The Attached well History and Recommondation. Plug AS Follows! 1. Lood Woll w/ Produced Water, 2. Run Thy with Squeeze Phr Set AT 4633' and Establish Pump Pote, 3, Pull Tbg + Sq. PKr 4. Run The with CMT Rotainer Sof AT 4633' + Squeeze with 200 FX Chass E" CMT and 2% CACK 2. 5. Pull out of Rotainer With Thy + Leave 25' OF CANT ON TOP OF Retainer, 6, Runthy apon onded. CMT From 1330- 900' Ë 30 SX Chiss SPOT 630'- 200' 8. Surface Plug 11 58 10 10. Exact Dry Hole Marker and Rostone The Surfac. 9, 18. I hereby certify that the foregoing is true and correct upt awus DATE SIGNED Nau TITLE (This space for Federal or State office use) APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY: BERNARD MOROZ *See Instructions on Reverse Side ACTING DISTRICT ENGINEER

4565	(5),	File	- (2)
•			

•

CIL COMPANY, M. M.

 ≤ 2 PRESENT STATUS T, SALT - 1221 Sec 19-235-33E B. SALT - 4773! 1980' FSL + 625' FWL ELEV- 3714 K.B. 75/8", 24" csg @ 367, W/2005x comment cir to sfe. Ŋ 4'12, 9.5" csg replaced to 1,186' W/150 st. TOC - 3800' 10:01 D'A esq hole + tubing fish @ 4683' 388' of 23/8", 4.7# +bg Cosing Perfs @ 5088-5098 W/ 4 HPF. 4'/2," 9.5t cg @ 5230' W/200 5% TOC @ 3800 TD. - 5230' BEE

MARSHALL NO 4 PRESENT STATUS

5/6/77

Completed 1/11/62

Cruz DELAWARE LEA COUNTY, NM

CIL COMPENSATION COMM. HOBBS, N. M.

.

COPOSED STATUS DARSHALL # 4 Sec 19, T-235, R-33E T. SALT - IZZI 1980'FSL & 625' FWL B. SOLT - 4773 "0"- 13' A4L LEA COUNTY, NEW MEXICO 3701 'GR 3714'D.F cement plug to sfe w/ 10 sx class "c" w/ 4" pipe - 4' AGL (marker) 75/8", 21 t csq @ 367', W/200 52. a comment cir to sfe. cerment plug from 200-630' W/30 SL. class "C" cmt. 41/2, 9,5 tcsg replaced cement plug from - 1007' W/ 30 sx closs "C" cmt. 10 1,186'W/150 SX TOC - 3800' 24 5. ¥ cement retainer & 4633', squeezed W/200 SX. Class "C" cmt. cog hole + tubing fish @ 4683' 388' of 2=18", 4,7# +bg. Casing perfs @ 5088-5098 W/4 HPF. 41/2", 9.5 # csg @ 5230' W/200 SX. T.D. - 5230 Completed 1/11/bz MARY BEE MACSHALL #4 Cruz Oclowore 5/9/77

PROPOSED STATUS

t

ALC 1 1977

CIL COMBER WATERN GOMM. HOBBS, N. M.

Woll History and Recommendation

Plug and Abandon Marshall No. 4

It is recommended that the Marshall No. 4 be plugged and abandoned due to the stuck tubing fish and the hole milled through the casing above the fish.

Initial Completion Data

Location: 1980' FSL & 625' FWL, Sec. 19, T23S, R33E, Lea County, N. M.

Completed: January 11, 1962

Elevation: 3714' K.B.

Total Depth: 5230'

Casing: 7 5/8" O.D., 24#/ft., set at 367' with 200 sacks, circulated. 4 1/2" O.D., 9.5#/ft., set at 5230' with 200 sacks, TOC at 3800'

Producing Interval: 5088'-5098'

Formation: Delaware Ramsey Sand

Initial Treatment: Natural

I.P. 158 BOPD, 41.4 MCFPD

Previous Remedial Work

The Marshall No. 4 is presently shut in with cumulative production to date at 141,239 BO. The producing rate prior to the casing leak was 30 BOPD and 21 BWPD.

Discussion

The Marshall No. 4 was drilled in 1962 and completed as an oil well in the Delaware Ramsey sand. In 1975, an attempt was made to mill out a tubing fish in the well bore, during which, the mill cut through the casing and started drilling outside the pipe. The well was subsequently shut in.

1.00 1 - 1977

CIL CONTRATION COMM. HOBBS, N. M. L. P. Thompson Page 2 July 21, 1977

Due to the condition of the well bore created by the above work, the chances of going back in and recovering the tubing fish are very slim. However, with the estimated remaining reserves of 40,000 BO at this location, a replacement well for Marshall No. 4 is justified. An AFE to drill the Marshall No. 8 as a replacement has been submitted.

Recommendation

Since the well bore of Marshall No. 4 can not be utilized for any purpose, it is recommended that the subject well be plugged and abandoned.

COL COMBER ON COMM. HOBBS, N. M.