

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 068848

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

CONTINENTAL OIL COMPANY

3. ADDRESS OF OPERATOR

Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FSL & 625' FWL OF SEC. 19

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

MARSHALL

9. WELL NO.

4

10. FIELD AND POOL OR WILDCAT

CRUZ DELAWARE

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC. 19, T. 23S, R. 33E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3701' DF

12. COUNTY OR PARISH

LEA

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☒ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent
to this work.)*

In August, 1975 a casing leak was found @ 1062'. While running a free-point, the 4 1/2" csq. parted @ 1,047'. Poor condition csq. to 1,186' was replaced with new 4 1/2" which was cemented and pressure tested satisfactorily. After completing the casing repair, an attempt was made to recover 486' tubing fish. Top of fish located @ 4585'. Part of fish was removed & milled out to 4683', at which point the mill apparently cut the 4 1/2" csq. The well is presently shut-in pending evaluation with 388' tubing fish remaining in well. Work started 8-20-75, suspended 9-11-75.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

SR. Analyst

DATE

10-10-75

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

USGS-5, FILE