ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION				
SANTA PE				
FILE				
U.S.G.S.				
LAND OFFICE				
OPERATOR	-			

## L CONSERVATION DIVISION

SANTA PE	SANTA FE, NEW MEXICO 87501		Revised 10-1-3
/ILE	-		5a. Indicate Type of Leuse
LAND OFFICE			Stale X Fee
GPERATOR	j		5. State Oil & Gas Lease No. A-2614
IDO NOT USE THIS FORM FOR PRO USE "APPLICAT	Y NOTICES AND REPORT	BILL BACK TO A DIFFERENCE SPECIAL	
1.  OIL	OTHER- Injection	Well	7. Unit Agreement Name . S. Eunice 7RQ Unit
Marathon Oil Com	pany		8. Farm or Lease Hame S. Eunice 7RQ Unit
P. O. Box 2409	Hobbs, NM 88240		9. Well No. 60.5
4. Location of Well	1980 s	outh - 1980 PEET	10. Field and Pool, or Wildcat S. Eunice 7RQ
	25 TOWNSHIP		PROM. (IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
	15. Elevation (Show w GR 3444,	hether DF, RT, GR, etc.) KB 3454	12. County Lea
Check A		ate Nature of Notice, Report o	r Other Data JENT REPORT OF:
PERFORM REMIDIAL WORK  TEMPORARILY ABAHOON  PULL OR ALTER CASING	PLUG AND ASANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING OPHS. CASING TEST AND CEMENT JQB OTHER	ALTERING CASING PLUG AND ABANDONMENT
OTHER		- 📙	
17. Describe Proposed or Completed Opwork) SEE RULE 1703.	erations (Clearly state all pertine	ent details, and give pertinent dates, incl	uding estimated date of starting any proposed
PURPOSE: PLUG A	ND ABANDON WATER INJE	CTION WELL	
1. Set CIBP at	3650'. Spot 40' of c	ement on top of plug.	
2. Pull tubing annulus.	to 1000'. Circulate	cement down tubing to sur	face between tubing-casing
3. Pull out of	hole with tubing.		
4. Remove BOP's	and cut off wellhead	•	
5. Set 10' cemen	nt plug at surface.		
6. Cap well with	h dryhole marker and	clean up location.	
		DECTOR OF THE CONTRACTOR OF TH	and e
8. I hereby certify that the information	shove is true and complete to the	best of my knowledge and belief.	
Thomas F. Zapatk	al Man & Zouth wire	Production Engineer	11-21-85
ORIGINAL SIGNED BY	REST SEXTON		DEC 1 2 1985
··	<del></del>		

NO. 53 400