

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 30-025-09044
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name S. Eunice 7RQ Unit
Well No. 301
Pool name or Wildcat S. Eunice 7RQ Unit
Well Location Unit Letter <u>F</u> : <u>2310</u> Feet From The <u>North</u> Line and <u>1650</u> Feet From The <u>West</u> Line Section <u>26</u> Township <u>22S</u> Range <u>36E</u> NMPM <u>Lea</u> County
Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3498 DF-3508

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

Name of Operator  
Marathon Oil Company

Address of Operator  
P.O. Box 2490 Hobbs, New Mexico 88240

Well Location  
Unit Letter F : 2310 Feet From The North Line and 1650 Feet From The West Line  
Section 26 Township 22S Range 36E NMPM Lea County  
Elevation (Show whether DF, RKB, RT, GR, etc.)  
GR-3498 DF-3508

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

06/27/00--Notify NMOCD of rig up & intent to plug  
06/28/00--Spot 25 sx C w/3% cact from 3650-3404, WOC, no tag, witnessed byh Bubby Hill(OCD)  
Spot 25 sx C cement from 3650-3404  
06/29/00--No tag  
07/03/00--Set CIBP @ 3600, circulate hole w/10# mud, spot 25 sx C cement from 3600-3354, spot  
25 sx C cement from 2221-1974, test 5 1/2 csg to 500 psi, held, perf @ 400, pump 35 sx C  
cement, displace to 300, shut in, WOC  
07/05/00--Tag plug @ 265, spot 10 sx surface plug from 60', RDMO  
07/11/00--Cut off well head, install dry hole marker, cut off anchors, clean location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry McBeth TITLE Key Energy P&A Supervisor DATE 07-11-00  
TYPE OR PRINT NAME Terry McBeth TELEPHONE NO. (915) 523-5155

(This space for State Use)

APPROVED BY [Signature] TITLE [Signature] DATE 6-18-01  
CONDITIONS OF APPROVAL IF ANY: [Signature]