

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

3-NMOCC
1-File

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator GETTY OIL COMPANY	8. Farm or Lease Name A. L. CHRISTMAS
3. Address of Operator P. O. BOX 249, HOBBS, NEW MEXICO	9. Well No. 1
4. Location of Well UNIT LETTER F 1650 FEET FROM THE NORTH LINE AND 1650 FEET FROM THE WEST LINE, SECTION 26 TOWNSHIP 25-S RANGE 36-E N.M.P.M.	10. Field and Pool, or Wildcat JALMAT POOL
15. Elevation (Show whether DF, RT, GR, etc.)	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rework not economically feasible. It is proposed to plug well and abandon lease as follows:

1. Set 100' cement plug in and out of 7" casing shoe. (Cement circulated to surface.)
2. Pump mud to approximately 1550'.
3. Set 100' cement plug at bottom of salt (approximately 1525').
4. Pump mud to surface.
5. Set 10 sack surface plug.
6. Set marker and clean up location.

24 hr. notice

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY:

SIGNED **C. L. Wade** **C. L. Wade** TITLE **AREA SUPERINTENDENT** DATE **AUGUST 7, 1972**

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

WLG/bh