

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease

State ☐ For ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- WIW	7. Unit Agreement Name
2. Name of Operator ARCO Oil and Gas Company Division of Atlantic Richfield Company	8. Farm or Lease Name Seven Rivers Queen Unit
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM THE <u>East</u> LINE, SECTION <u>27</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat Eunice Seven Rivers Queen South
15. Elevation (Show whether DF, RT, GR, etc.) 3501' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.


1. Rig up, POH w/injection assy, install BOP. CO w/bit to 3817' PBD..
2. Set pkr @ 3675' & acidize perms 3726-30', 3740-48', 3752-54', 3764-70', 3780-90', 3792-98' w/6000 gals 15% NEA in 5 equal stages. POH w/pkr.
3. Perf add'l holes 3695-3700' & 3705-11' w/l JSPF. Set RBP @ 3720' & pkr @ 3645'. Acidize perms 3695-3700' & 3705-3711' w/2500 gals 15% NEA.
4. POH w/RBP & pkr. RIH w/pkr, set pkr @ 3645' & swab back load. POH w/pkr.
5. RIH w/pkr & inj assy, set pkr @ 3630' & resume injection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Roland W. Lawrence TITLE Drlg. Engr. DATE 9/03/82

APPROVED BY Eddie W. Lawrence TITLE OIL & GAS INSPECTOR DATE SEP 10 1982

CONDITIONS OF APPROVAL, IF ANY:



ARCO Oil & Gas Company

Division of Atlantic Richfield Company

Blow Out Preventer Program

Lease Name Seven Rivers Queen Unit

Well No. 1

Location 330' FNL & 990' FEL
Sec 27, 22S-36E, Lea County

BOP to be tested when installed on well and will be maintained in good working condition during drilling. All wellhead fittings to be of sufficient pressure to operate in a safe manner.