STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

Erior and transcende		
	Ĭ	
DISTRIBUTION		<u>L</u> .
SANTAFE		<u> </u>
FILE	-	1
U.S.G.S.		↓
LAND OFFICE		<u> </u>
DPERATOR	ł	1

CONDITIONS OF APPROVAL, IF DISTRICT ! SUPR.

OIL CONSERVATION DIVISION

DISTRIBUTION		P. O. BOX 2088			Revised 10-1-78		
SANTAFE	SANTA F	E, NEW N	MEXICO 87501		Indicate Type	of Lease	 -
V.S.O.S.				34.	State	For	(X)
LAND OFFICE	}			5.	State Off & Ga		
DPERATOR							1
				/_	mm	THITT	777
SUNDRY NOTICES AND REPORTS ON WELLS THIS FORM FOR PROPOSALS TO DRILL ON TO DECERN OR PLUG BACK TO A DIFFERENT RESERVOIR.					11111		
USC "APPLICAT	ION FOR PERMIT -** (FORM C-10	II) FOR BUCH	PROPESALS.I	7.	Unii Agreemen	t Name	
OIL CAS		WIW					
WELL WELL WELL	OTHER-	MIM		8.	Farm or Lease	Name	
ARCO Oil and Gas Company, Division of Atlantic Richfield Company				S	Seven Rivers Queen Ut.		
ARCO OIL and Gas Compa	ily, Division of he	Tancie .		9.	Well No.		Ì
	New Mexico 88240				9		
P. O. Box 1710, Hobbs, New Mexico 88240				10. Field and Pool, or Wildcat			
UNIT LETTER I 1980 FEET FROM THE South LINE AND 660 FEET FROM			EET FROM	Eunice SRO South			
				1/			
THE East LINE, SECTION	ON 27 TOWNSHIP	22S	RANGE36E	имрм. 🚫			
THE LINE, SECTION					. County	7,1414	HH,
15. Elevation (Show whether DF, RT, GR, etc.)			i	Lea		VIII.	
		3517 '					7777
16. Check	Appropriate Box To In	dicate Na	ature of Notice, Repor	t or Other	Data		
	NTENTION TO:		SUBSE	EQUENT R	EPORT OF	1	
· .						RING CASING	П
PERFORM REMEDIAL WORK	PLUG AND AB	ANDON L	REMEDIAL WORK			AND ABANDONME	H
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS.	H	7200		
PULL OR ALTER CASING	CHANGE PLAN	•	CASING TEST AND CEMENT JQB				\Box
			OTHER				
OTHER							
17. Describe Proposed or Completed O	perations (Clearly state all p	ertinent deta	ils, and give pertinent dates,	including est	imated date of	starting any p	roposea
work) SEE RULE 1103.							
Rigged up on 10/11/82, 3707-3804' in 7 equal 3618', test to 1000#, 3673-79' & 3684-90' w/w/135 gals gelled bring CO sd & tagged btm @ 3tbg/csg annulus w/pkr BW, TP 1100#, CP 0#. I	stages of 1000 gal OK. POH w/BP. Spot /1 JSPF. Set pkr @ ne, 3000 gals 15% N 3812'. RIH w/AD-1 p fluid. Returned to	Ls 15% N. 21 sx 3618', [EA usin	sd. Top of sd @ 37 acidized perfs 367 ag RS between stage	700'. Per 73-79' & es. On va	f'd addi 3684-90' ac.POH w/	tional SR in 3 sta tbg & pkr 635'. Cir	· ·
			of my knowledge and belief.				A ^A
18. I hereby certify that the information	in above is true and complete						
PO- 1.11.	1864 11		Drlg Engr		DATE 1	0/28/82	
BIENEO CE alupe	A Vupic	TITLE					
ORH	GINAL SIGNED BY	•				NOVS	198