

- ⑧ Acidize w/ 120 bbls 15% HCL-NE-FE, Flush w/ 60 bbls 2% KCL TFW w/ 1 gal Adomall/1000 gals.
- ⑨ Return well to injection Do not exceed 600 psi surf. pressure. Rig down.