

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State ☒ (Fed) Fee ☐
5. State Oil & Gas Lease No.	LC-030133(B)

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER: <u>Injection</u>	7. Unit Agreement Name
2. Name of Operator CONOCO INC.	8. Farm or Lease Name <u>South Eunice Unit</u>
3. Address of Operator P. O. Box 460, Hobbs, N.M. 88240	9. Well No. <u>41</u>
4. Location of Well UNIT LETTER <u>E</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>28</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> N.M.P.M.	10. Field and Pool, or Wildcat <u>Eunice 7 Rvs Queen So.</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒	CASING TEST AND CEMENT JOBS ☐	

Modify injection profile by installing liner from surf. to top of flood zone to isolate flood zone.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU, Release pkr @ 3556' & POOH. Clean out to 3804' (PBTD)
- Plug well back from 3804'-3670' w/ 18 ft³ pea gravel. Dump 10' Cal-Seal plug from 3670'-3660'. Set retainer @ 3550'.
- Pump 200 sxs Class "C" w/ 2% CaCl₂. Displace w/ 14 bbls 2% KCL TFW.
- WOC 24 hrs. Drill out retainer & cmt to 3660'. Prepare to run liner.
- GIH w/ 4", 10.46# FJ guide shoe, 1/4" 4", 10.46# FJ FL-45 liner, 4", 10.46# FJ float collar, and 4", 10.46# J-55 FJ FL-45 liner. Land guide shoe @ 3655'.
- Pump 50 bbls 2% KCL TFW nitrified w/ 180 scf/bbl down liner to establish circ. Pump 100 sxs class "C" cmt w/ 2% CaCl₂ nitrified w/ 180 scf w/ 10. foamer & 5 gal foam stabilizer, pump 50 sxs class "C" cmt w/ 2% CaCl₂. Release 4", 10.46# csg wiper plug & displace cmt w/ 43 bbls 10 ppg brine. Pump 20 sxs class "C" Thix-o-tropic to cap foam cmt. WOC 24 hrs.
- DO cmt to 3660' and press. test to 1000 psi. Drill out Cal-Seal plug Cont

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Administrative Supervisor DATE 8-7-86

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY

TITLE

DATE

AUG 11 1986

NMOLD-Hobb.
File

RECEIVED
AUG 8 1986
O.F.D.
HOBBS OFFICE