MEYER B-28 No. 2 PLUG AND ABANDON

990' FNL & 990' FEL, Sec. 28, T-22S, R-36E Location: Lea County, NM

3510' DF (10' AGL) Elevation:

Completion: Jalmat Yates Seven Rivers TD: 3575' 4-3/4" Open Hole (3034'-3575')

> Lane Wells retrievable packer w/Guiberson holddown set at 2971'.

> This is a compression set packer with a Note: straight pick up to release (8-30" stroke).

Casing/Tubing Specifications:

O.D.	Weight Gra	de Depth	Drift	Collapse	Burst	Capacity ₃	
(in)	(lbs/ft)	(ft)	(in)	(psi)	(psi)	(bbl/ft)	<u>(ft'/ft)</u>
	32.75 H-4					.1009	.5665
5-1/2"	17.0 J-5	5 3034	4.767	4,910	5,320	.0232	.1305
2-7/8"	6.5 N-8	0	2.347	11,160	10,570	.00579	.03250

10-3/4" casing set @ 335' with 250 sx cement circulated to surface. 5-1/2" casing set @ 3034' with 1100 sx cement. TOC @ 216' by temperature survey. Repaired casing leak @ 165'-200' with 168 sx cement. Cement circulated to surface out 10-3/4" casing. Use safety factor of 70% for collapse and burst pressures. Assume 2-7/8" workstring will be used.

Notes: 1. All cement slurry used in this procedure shall be Class "C" with 2% CaCl, mixed @ 14.8 ppg. 2. All mud shall be 9.5 ppg with 25 lbs gel/bbl brine.

3. Call Kandy Lawson to notify BLM prior to commencing any work.

Recommended Procedure:

- 1. Prepare well for P&A:
 - A. MIRU. Bleed well pressure down. Kill well with 10 ppg brine if needed.
 - B. ND wellhead and NU BOP. Release packer (Beat on coming up. Pull 50-70 pts. tension on tubing and let set overnight if needed).
 - C. If this fails, RU wireline services and cut production tubing off 10'-15' above packer.
 - D. TOOH and LD 2-3/8" production tubing.