Meyer B-28 No. 2 Plug and Abandon Page 3

2. Marker must be capped and inscribed with the following well information:

Meyer B-28 No. 2 Unit A, Sec. 28, T-22S, R-36E Lea County, NM Date

- Note: 1/4" metal plate can be welded to marker and then to the casing after the marker is set in cement.
- E. Cut off dead-man anchors below ground level and remove markers. Fill in cellar and workover pit.
- F. Remove all equipment, concrete bases, and pipe not in use.
- G. Clean and restore location to its natural state. Reseed according to BLM requirements.
- 5. Send a copy of the well service report and final P&A schematic to Kandy Lawson in the Hobbs Office so the proper forms can be filed.

Approved:

Tom C. aduddell

Engineering Technician

sh a. miller Enginee

Supervising Production Engineer

Mullad Moun

Division Engineering Manager

Production Superintendent

TCA:mjm MB-28NO2.PRO

<u>2-2-90</u> Date

2-3-90 Date

Date

3-19-90

Date