

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER Injection
2. NAME OF OPERATOR Conoco Inc.
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, NM 88240
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
Unit 6 1980' FNL & 1980' FEL
14. PERMIT NO. 30-025-09079
15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5. MAY 24 10 37 AM '90
CARL
AREA

6. LEASE DESIGNATION AND SERIAL NO. LC-030133B
7. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME South Eunice Unit
8. FARM OR LEASE NAME
9. WELL NO. #39
10. FIELD AND POOL, OR WILDCAT Eunice 7 Ruro Queen So.
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 28-225-36E
12. COUNTY OR PARISH Lea
13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) Install Liner, PB to 3754'
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

3/29/90 Install BOP. 61H w/85 fts. 4" Csg. Tagged @ 3613'. P.U. to 3610'. Pumped 200 sks. Class 'C' cmt w/2% CaCl₂ mitigated w/180 scf/bbl w/10gal foamers. Pump 50 sks. Class 'C' w/2% CaCl₂. WOC 61H w/bit, tagged @ 2870'. D.O. cmt to PBT D 3760'. Circ. hole clean. 61H w 1/2 sk. Calsed. WOC 1 hour. Tagged top @ 3754'. Set pki. @ 3537'. Load & test backside to 500#. Held. Slim. 7 Ruro Queen. 3622-3807' w/90 BULs 15% HCL-NE-FE. Flushed, swabbed. Run inj. equip. Circ. hole w/90 bbls pkn fluid. Test Csg. to 500# for 30 min. Held.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Conservation Coord. DATE 5/20/90

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE [Signature] DATE [Signature]
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side