

Copy For Well File

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

32-025-09255

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

B. A. CHRISTMAS

8. Well No.

1

9. Pool name or Wildcat

JALMAT (TANSILL, YT, 7-RIV)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☐

GAS  
WELL ☒

OTHER

2. Name of Operator

MERIDIAN OIL INC

3. Address of Operator

P.O. Box 51810, Midland, TX 79710-1810

4. Well Location

Unit Letter L : 1650 Feet From The South Line and 330 Feet From The WEST Line

Section 28

Township 22-S

Range 36-E

NMPM LEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3508' GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MI RU, NU BOPE. POOH W/ 2-3/8" TUBING.

RIH W/ 2-3/8" TUBING, BIT AND SCRAPER. POOH.

RIH W/ 5 1/2" 17# CIBP ON TUBING AND SET @ 3086'. DISPLACE HOLE W/ 10 PPG GELLED BRINE MUD. MIX AND SPOT 25 SX CL C PLUG ON CIBP. POOH.


PERF 4 SQUEEZE HOLES @ 1740'-41'. RIH W/ 2-3/8" TUBING AND 5-1/2" CIBP AND SET @ 1640'. SQUEEZE 50 SX CL C BELOW CIBP. STING OUT OF PLUG AND CAP W/ 6 SX.

PU HOLE TO +/- 356' AND SPOT 36 SX CL C PLUG FROM 356' TO SURFACE. POOH. RD MO.

CUT CASING OFF 3' BELOW SURFACE. WELD STEEL PLATE AND P & A MONUMENT TO CASING STUB. RESTORE SURFACE AS DIRECTED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE



TITLE Production Asst.

DATE 11-17-93

TYPE OR PRINT NAME DONNA WILLIAMS

TELEPHONE NO. 915/688-6943

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

JAN 06 1994

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: