

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 300250908700
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Water Injection	7. Lease Name or Unit Agreement Name South Eunice Unit
2. Name of Operator Conoco Inc.	8. Well No. 47
3. Address of Operator 10 Desta Drive West, Midland, TX 79705	9. Pool name or Wildcat Eunice 7-Rivers Queen South
4. Well Location Unit Letter I : 2210 Feet From The south Line and 330 Feet From The east Line Section 28 Township 22S Range 36E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 3492'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: Install liner <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to install a 4" steel liner, stimulate the injection interval, and return this well to injection by the following procedure:

1. RIH with bit and casing scraper and clean out any fill.
2. Run 4" FJ steel liner to 3800' (TD) and cement in place with 250 sxs cement.
3. Perforate 7-Rivers zones 1-3 at 3608'-9', 3619'-20', 3630'-31' with 1 JSPF and 3657'-64', 3673'-80', 3698'-3700', 3710'-20', 3725'-34' with 4 JSPF.
4. Acidize with 90 bbls 15% HCL acid.
5. Return to injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry W. Hoover TITLE Regulatory Coordinator DATE 12-4-90  
TYPE OR PRINT NAME Jerry W. Hoover TELEPHONE NO. 915-686-6548

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: