

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Inj. Well</u>	7. Unit Agreement Name <u>South Eunice Unit</u>
2. Name of Operator <u>CONOCO INC.</u>	8. Farm or Lease Name <u>South Eunice Unit</u>
3. Address of Operator <u>P. O. Box 460, Hobbs, N.M. 88240</u>	9. Well No. <u>47</u>
4. Location of Well UNIT LETTER <u>I</u> , <u>2210</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>28</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat <u>S. Eunice 7 Rvrs. Qun.</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <u>Lea</u>

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

OTHER repair csg leak ☒

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

MIRU. Rel pkr. Set RBP @ 3460' & dump 1 sk sand on top. Isolate csg. leak w/ treating pkr. POOH w/ pkr. Set cmt ret. @ 50' above csg leak. Pump 200 sxs class "C" cmt w/ 2% CaCl<sub>2</sub>. Flush w/ 1/2 bbl. water per 100' thg in hole or 2 bbls water per 100' open csg above hole. WOC. DO ret & cmt. Press test sqe to 500 psi. Resqueeze if necessary. Circ sand off RBP @ 3460' & rel. CO to 3800'. Set pkr @ 3465' & place well back on inj.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Kevin L. Boyd

Administrative Supervisor

DATE 8/21/85

ORIGINAL SIGNED BY JOHN SEXTON

AUG 23 1985

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 22 1985

O.C.D.  
HOBBS OFFICE